

	Type	L #	Hits	Search Text	DBs	Time Stamp
7	BRS	L7	242	(induction with hardening with (work-piece or workpiece or (work near piece)))	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:35
8	BRS	L8	459	(edge with (work-piece or workpiece or (work near piece))) and (measur\$3 with (first and second))	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:54
9	BRS	L9	1	7 and 8	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:15
10	BRS	L10	5	7 and (measur\$3 with (first and second))	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:24
11	BRS	L11	0	7 and (measur\$3 near hardening)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:24
12	BRS	L12	2	7 and (measur\$3 near hardness)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:35

	Type	L #	Hits	Search Text	DBs	Time Stamp
13	BRS	L13	98	(edge with (work-piece or workpiece or (work near piece))) and (measur\$3 with hardness)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:51
14	BRS	L14	4	13 and (induction with heat\$3)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:27
15	BRS	L15	3139	(induction with hardening)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:15
16	BRS	L16	39	15 and (measur\$3 near hardness)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:54
17	BRS	L17	1	16 and (elongat\$3 with (work-piece or workpiece or (work near piece))) and (measur\$3 with hardness)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:52
18	BRS	L18	1	16 and (elongat\$3 with (work-piece\$1 or workpiece\$1 or (work near piece\$1))) and (measur\$3 with hardness)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:15

	Type	L #	Hits	Search Text	DBs	Time Stamp
19	BRS	L19	1	(16 and (work-piece or workpiece or (work near piece))) and (measur\$3 with (first and second))	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 17:55
20	BRS	L20	5	(16 and (work-piece or workpiece or (work near piece)))	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:15
21	IS&R	L21	1	("3738636").PN.	USPAT	2004/10/07 18:03
22	BRS	L22	4	("2794894" "3648995" "0947174" "2679177").PN.	USPAT	2004/10/07 18:08
23	BRS	L23	0	22 and (measur\$3 with hardness)	USPAT	2004/10/07 18:16
24	BRS	L24	3	269/\$.ccls. and (measur\$3 with hardness)	USPAT	2004/10/07 18:11
25	IS&R	L27	1011	(219/635,601,639,656).CCLS.	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:13
26	IS&R	L28	326	(169/49,30,114,145,224,227,254R).CC LS.	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:13
27	IS&R	L29	674	(266/129,131,125).CCLS.	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:14

	Type	L #	Hits	Search Text	DBs	Time Stamp
28	IS&R	L30	339	(148/328).CCLS.	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:14
29	IS&R	L31	423	(29/244).CCLS.	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:14
30	IS&R	L32	257	(474/8).CCLS.	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:14
31	BRS	L33	2930	27 or 28 or 29 or 30 or 31 or 32	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:15
32	BRS	L34	163	33 and (induction with hardening)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:20
33	BRS	L35	1	34 and (elongat\$3 with (work-piece\$1 or workpiece\$1 or (work near piece\$1))) and (measur\$3 with hardness)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:15

	Type	L #	Hits	Search Text	DBs	Time Stamp
34	BRS	L36	88	(34 and (work-piece or workpiece or (work near piece)))	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:16
35	BRS	L37	4	36 and (measur\$3 with hardness)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:20
36	BRS	L38	0	34 and (metal with (blade\$1 or knife\$1))	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:20
37	BRS	L39	3139	(induction with hardening)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:20
38	BRS	L41	0	40 and (measur\$3 with hardness)	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:20
39	BRS	L40	21	39 and (metal with (blade\$1 or knife\$1))	USPAT; US-PGP UB; EPO; JPO; DERWE NT	2004/10/07 18:20